POZNAN UNIVERSITY OF TECHNOLOGY



EUROPEAN CREDIT TRANSFER AND ACCUMULATION SYSTEM (ECTS)

pl. M. Skłodowskiej-Curie 5, 60-965 Poznań

COURSE DESCRIPTION CARD - SYLLABUS

Course name

Metrology and measurement systems

Course

Field of study Year/Semester

Mechatronics 2/3

Area of study (specialization) Profile of study

general academic

Level of study Course offered in

First-cycle studies polish

Form of study Requirements full-time compulsory

Number of hours

Lecture Laboratory classes Other (e.g. online)

15 15 0

Tutorials Projects/seminars

15 0

Number of credit points

4

Lecturers

Responsible for the course/lecturer: Responsible for the course/lecturer:

Ph.D. Radomir Majchrowski

email: radomir.majchrowsk@put.poznan.pl

tel. 61 665 3223

FACULTY OF MECHANICAL ENGINEERING

Prerequisites

Knowledge: knowledge of mathematical statistics, technical drawing and machine parts

Skills: logical thinking, using information from the library and the Internet

Social competencies: understanding the need for learning and acquire new knowledge

Course objective

Adapting basic concepts from measurement techniques. Get acquainted with measuring instruments and methods and measuring systems used in machine construction. Acquire the ability to calculate engineering tolerances of inner and outer features of cylinder bores, drilled holes, linear and precision shafts, pistons, thread etc. Ability to estimate uncertainty of measurement. A and B type uncertainty estimates.

POZNAN UNIVERSITY OF TECHNOLOGY



EUROPEAN CREDIT TRANSFER AND ACCUMULATION SYSTEM (ECTS)

pl. M. Skłodowskiej-Curie 5, 60-965 Poznań

Course-related learning outcomes

Knowledge

Student knows basic concepts of measurement techniques - K W13.

Student knows measurement methods and measuring systems used in machine construction - K_W13.

Student knows basic measuring equipment used for measuring machine parts - K W13.

Skills

Student is able to calculate and select tolerances and symbols for holes and shafts, threads and other machine parts - K_U17

Student knows the hierarchy of standards and can choose measuring instruments for measuring machine parts - K U17

Student is able to calculate the uncertainty of measurements using the A and B method - K U17.

Student is able to calculate the uncertainty for indirect measurements - K U17.

Social competences

1Student is aware of the importance and understanding of non-technical aspects and effects of engineering activities, including its environmental impact and the resulting responsibility for its decisions - K_K02

Student can cooperate and work in a group - K_K03

Methods for verifying learning outcomes and assessment criteria

Learning outcomes presented above are verified as follows:

Lecture: Passing on the basis of an examination (test), conducted at the end of the semester.

Laboratory: Passed on the basis of a written answer in the scope of content. Performed the laboratory exercises according to the program established by the teacher with a positive grade of the reports on the six exercises prepared according to the subject matter

Classes: Passing on the basis of a colloquiums.

Programme content

Lecture:

- 1. Measurement theory, measurement result, estimating uncertainty from measurement
- 2. Etalons, standards of length and angle, gauge block, angular gauge block, hierarchies of standards
- 3. Measurement instruments of length and angle measurements calipers, micrometers, sensors
- 4. Tolerance and fit system (shaft and holes measurement)
- 5. Measurement of external and internal threads

POZNAN UNIVERSITY OF TECHNOLOGY



EUROPEAN CREDIT TRANSFER AND ACCUMULATION SYSTEM (ECTS)

pl. M. Skłodowskiej-Curie 5, 60-965 Poznań

- 6. Methods of measurement for angles and cones
- 7. Measurements of shape deviations and position, measurements of surface roughness
- 8. Introduction to CMM

Laboratory:

- 1) Tolerances and fits.
- 2) Calculation of measurement uncertainty.
- 3) Checking measuring instruments (micrometer).
- 4) Contact and optical thread measurements.
- 5) Statistical analysis of the measurement results.
- 6) Measurement of shape deviations.
- 7) Introduction to the coordinate technique.

Classes:

Tolerance and fit system, estimating uncertainty from measurement

Teaching methods

Lecture: presentation illustrated with examples given on the blackboard, solving problems.

Bibliography

Basic

Paczyński P.: Metrologia techniczna. Przewodnik do wykładów ćwiczeń i laboratoriów. Wyd. Zakład Metrologii i Systemów Pomiarowych, Politechnika Poznańska, Poznań 2003.

Adamczak S., Makieła W.: Metrologia w budowie maszyn. Zadania z rozwiązaniami. Politechnika Świętokrzyska, Kielce 2001.

Arendarski J.: Niepewność pomiarów. Oficyna Wydawnicza Politechniki Warszawskiej, Warszawa 2000.

Humienny Z., Osanna P.H., Tamre M., Weckenmann A., Blunt L., Jakubiec W.: Specyfikacja geometrii wyrobów (GPS). WNT, Warszawa 2004.

Jakubiec W.: Malinowski J.: Metrologia wielkości geometrycznych. WNT, Warszawa 1999.

Additional

Jezierski J.: Analiza tolerancji i niedokładności w budowie maszyn. WNT, Warszawa 1994.

Malinowski J.: Pomiary długości kąta. Wyd. Szkol. i Pedag., wydanie 3-cie, Warszawa 1993.Malinowski J.





EUROPEAN CREDIT TRANSFER AND ACCUMULATION SYSTEM (ECTS)

pl. M. Skłodowskiej-Curie 5, 60-965 Poznań

Jakubiec W., Płowucha W.: Pomiary gwintów w budowie maszyn, WNT, 2009

Ratajczyk E.: Współrzędnościowa technika pomiarowa, Wyd. Politechniki Warszawskiej, 2005

Pawlus P.: Topografia powierzchni: pomiar, analiza, oddziaływanie, Oficyna Wydawnicza Politechniki Rzeszowskiej, 2005

Sładek J.: Dokładność pomiarów współrzędnościowych, Politechnika Krakowska, 2012

Wieczorowski M.: Wykorzystanie analizy topograficznej w pomiarach nierówności powierzchni, Wydawnictwo Politechniki Poznańskiej, 2009

Breakdown of average student's workload

	Hours	ECTS
Total workload	100	4,0
Classes requiring direct contact with the teacher	65	3,0
Student's own work (literature studies, preparation for laboratory	35	1,0
classes/tutorials, preparation for tests/exam, project preparation) ¹		

-

¹ delete or add other activities as appropriate